

AD-A271 861



REPAIR, EVALUATION, MAINTENANCE, AND
REHABILITATION RESEARCH PROGRAM

2

US Army Corps
of Engineers

SUPPLEMENT TO TECHNICAL REPORT REMR-OM-08

REMR MANAGEMENT SYSTEMS—NAVIGATION STRUCTURES

MANAGEMENT SYSTEM
FOR
MITER LOCK GATES

by

Lowell Greimann, James Stecker, and Kevin Rens
Engineering Research Institute
Iowa State University
Ames, Iowa 50011



DTIC
ELECTE
NOV 02 1993
S B D

June 1993

Final Report


Approved For Public Release; Distribution Unlimited

Prepared for DEPARTMENT OF THE ARMY
US Army Corps of Engineers
Washington, DC 20314-1000

Under Contract No. DACA 88-91-32280
Under Civil Works Research Work Unit 32280

Monitored by Engineering and Materials Division
US Army Construction Engineering Research Laboratories
PO Box 9005, Champaign, Illinois 61826-9005

93 10 00 067



93-26333



**Best
Available
Copy**

The following two letters used as part of the number designating technical reports of research published under the Repair, Evaluation, Maintenance, and Rehabilitation (REMR) Research Program identify the problem area under which the report was prepared:

<u>Problem Area</u>		<u>Problem Area</u>	
CS	Concrete and Steel Structures	EM	Electrical and Mechanical
GT	Geotechnical	EI	Environmental Impacts
HY	Hydraulics	OM	Operations Management
CO	Coastal		

Destroy this report when no longer needed. Do not return it to the originator.

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products.

COVER PHOTOS:

TQP - Wilson Lock, Muscle Shoals, Alabama.
BOTTOM - Lock No. 19, Keokuk, Iowa.

REPORT DOCUMENTATION PAGEForm Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave Blank)		2. REPORT DATE June 1993		3. REPORT TYPE AND DATES COVERED Final	
4. TITLE AND SUBTITLE REMR Management Systems Navigation Structures Management System for Miter Lock Gates				5. FUNDING NUMBERS Civil Works Research Unit 32280	
6. AUTHOR(S) Lowell Greimann, James Stecker, and Kevin Rens					
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Engineering Research Inst. Iowa State University Ames, Iowa 50011				8. PERFORMING ORGANIZATION REPORT NUMBER Supplement to REMR-OM-08	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army Construction Engineering Research Laboratories P.O. Box 9005 Champaign, IL 61826-9005				10. SPONSORING/MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES Copies are available from the National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161. Software is available from U.S. Army Engineer Waterways Experiment Station, ATTN: CEWES-IM-DS, 3909 Halls Ferry Road, Vicksburg, MS 39180-6199 (telephone [601] 634-2581).					
12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited.				12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) The U.S. Army Corps of Engineers established a Repair, Evaluation, Maintenance, and Rehabilitation (REMR) program to focus more attention on deterioration and maintenance rates of civil works structures. An Iowa State University (ISU) research team has implemented this program and developed rating and maintenance procedures for miter lock structures as well as other structural components. This supplement describes and documents updates to the original inspection procedure and rating rules for miter lock gate structures. The changes have been recommended by Corps personnel as a consequence of the application of the initial procedure.					
14. SUBJECT TERMS navigation structures locks(waterways) REMR concrete preventive maintenance miter lock gates				15. NUMBER OF PAGES 36	
				16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT Unclassified		18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified		19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	
				20. LIMITATION OF ABSTRACT SAR	

PREFACE

This study was authorized by Headquarters, US Army Corps of Engineers (HQUSACE) under Civil Works Research Unit 32280, "Development of Uniform Evaluation for Procedures/Condition Index for Deteriorated Structures and Equipment," for which Dr. Anthony M. Kao is Principal Investigator. This work unit is part of the Operations Management problem area of the Repair, Evaluation, Maintenance, and Rehabilitation (REMR) Research Program sponsored by HQUSACE. Mr. James E. Crews (CECW-O) is the REMR Technical Monitor for this work.

Mr. Jesse A. Pfeiffer, Jr. (CERD-C) is the REMR Coordinator at the Directorate of Research and Development, HQUSACE; Mr. Crews and Dr. Tony C. Liu (CECW-ED) serve as the REMR Overview Committee; Mr. William F. McCleese (CEWES-SC-A), US Army Engineer Waterways Experiment Station, is the REMR Program Manager. Dr. Kao is also the Problem Area Leader for the Operations Management problem area.

The study was performed by the College of Engineering, Iowa State University, under contract to the US Army Construction Engineering Research Laboratories (USACERL). Principal Investigators for Iowa State University were Professors Lowell Greimann and James Stecker. Kevin Rens was the research assistant.

In 1990, inspection procedures and condition index rating rules for miter gates were published in REMR Management Systems-Navigation Structures, Management System for Miter Lock Gates, Technical Report REMR-OM-08. Since that document was published, updates to the rules and procedures have been made to reflect input by several Corps of Engineers personnel. The updated rules are described in this supplement.

The study was conducted under the general supervision of Dr. Paul A. Howdysshell, Chief of Engineering and Materials Division (EM) of USACERL, and under the direct supervision of Dr. Kao, CECER-EM, who was the Contracting Officer's Representative. The USACERL technical editor was Gloria Wienke, Information Management Office.

COL Daniel Waldo, Jr., is Commander and Director of USACERL and Dr. L.R. Shaffer is Technical Director.

DISCLOSURE: UNCLASSIFIED

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	

CONTENTS

	<u>Page</u>
PREFACE	1
CONVERSION FACTORS, NON-SI TO SI (METRIC) UNITS OF MEASUREMENT	2
PART I: INTRODUCTION	3
Background	3
Motivation for Updates	3
Supporting Material	4
PART II: FIELD INSPECTION	8
Overview of the Inspection Form	8
Sequence of Field Inspection	11
PART III: CONDITION INDEX	15
Distress Code (1): Top Anchorage Movement	15
Distress Code (2): Elevation Change	16
Distress Code (3): Miter offset	16
Distress Code (4): Bearing Gaps	17
Distress Code (5): Downstream Movement	18
Distress Code (6): Cracks	18
Distress Code (7): Leaks and Boils	18
Distress Code (8): Dents	18
Distress Code (9): Noise, Jump, and Vibration	18
Distress Code (10): Corrosion	18
PART IV: STRUCTURAL CONSIDERATIONS	19
Summary Report	19
REFERENCES	24
APPENDIX: SAMPLE INSPECTION FORM	A1

CONVERSION FACTORS, NON-SI TO SI (METRIC) UNITS OF MEASUREMENT

Non-SI units of measurement used in this report can be converted to SI (metric) units as follows:

Multiply	By	To Obtain
feet	0.3048	metres
inches	0.0254	metres

REMR MANAGEMENT SYSTEMS NAVIGATION STRUCTURES
MANAGEMENT SYSTEM FOR MITER LOCK GATES

PART 1: INTRODUCTION

Background

The US Army Corps of Engineers established a Repair, Evaluation, Maintenance, and Rehabilitation (REMR) program to focus more attention on deterioration and maintenance rates of civil works structures. An Iowa State University (ISU) research team has implemented this program and developed rating and maintenance procedures for miter lock gate structures (Greimann, Stecker, and Rens 1990) as well as other structural components. The purpose of this supplement is to describe and document updates to the original inspection procedure and rating rules for miter lock gate structures. The changes have been recommended by Corps personnel as a consequence of the application of the initial procedure.

The concepts and ideas for the inspection and rating of miter lock gates is based on previous work for steel sheet pile structures (Greimann and Stecker, 1990). Structural adequacy was measured by a factor of safety that formed the basis for the structural condition index. The factor of safety for miter gates was calculated by structural analysis software (US Army Corps of Engineers, 1987). Serviceability considerations and subjective judgments about safety were combined into a functional condition index, which was based on field measurements of distresses and opinions of experts. An engineer may judge that a safety problem is likely even though it is not quantifiable by measurements or simple calculations. For example, cracks or dents may be critical or noncritical, depending on the location and orientation.

Motivation for Updates

During the validation and training of the miter lock gate maintenance and repair program, it became clear that a structural analysis of horizontally framed gates could not be performed for a large number of gates. The assumptions that went into the development of the structural analysis software were valid for only a particular type of gate configuration. Additionally, the software performed a structural analysis of the as-designed structure as detailed in construction drawings and not the current in-place structure. Deterioration due to cracks, dents, corrosion, and wear were not accounted for in the software. In summary, the structural analysis did not seem to be warranted. The software does, however, evaluate the as-designed structures based on 1987 allowable stress design criteria.

Additionally, structural analysis software for vertically framed gates and many other structures in a navigation lock system is not available.

After several meetings with Corps personnel, it became clear that many structural considerations were already embedded in the functional rules in the form of subjective safety, as mentioned in the previous paragraphs. The experts took many structural factors into account when setting limiting values, tolerances, and weight factors. For example, embedded anchorage movement and contact offset of the miter blocks were really indicators of structural problems. With this in mind, it was decided that, in lieu of the structural factor of safety calculation, the current structural adequacy could be better described by some of the distress measurements. All the distresses and descriptions are listed in Table 1. Table 2 lists the separate sub-distresses contained within each distress (Greimann, Stecker, and Rens 1990). A subset of distresses were selected from Table 2 that have a more significant impact on safety (Table 3). The structural condition index, as such, will be discontinued and structural problems will be indicated on the distress list if the distress measurement exceeds certain bounds. A structural note along with the corresponding measurement will be included in the summary report to flag potential structural problems. A structural analysis is left as an option to the user but is not included as a part of the condition index calculation. The functional condition index will, henceforth, be referred to as the condition index; the word functional has been dropped.

Supporting Material

For management purposes, the condition index scale (0 to 100) is calibrated to group structures into three basic categories or zones. For the lowest zone (0 to 39) a detailed evaluation is required to determine the need for repair, rehabilitation, or reconstruction. As part of this evaluation, the tactics described in Engineer Technical Letter No. 1110-2-532, Reliability Assessment of Navigation Structures, dated 1 May, 1992, should be used.

Table 1
Distresses for Miter Lock Gates

Distress	Brief Description
Anchorage movement	Motion of the upper anchorage system during gate operation
Elevation change	Vertical displacement of the gate during operation
Miter offset	Misalignment of the bearing blocks at the miter point
Bearing gaps	Gaps between the bearing blocks at the quoin and miter
Downstream movement	Downstream displacement of the miter point as the head is applied
Cracks	Breaks in the structural steel components
Leaks, boils	Water passing through or around the gate
Dents	Misfiguration of steel components
Noise, jump, vibration	Abnormal noise, vibration, or jumping during gate operation
Corrosion	Loss of steel due to interaction with the environment

Table 1
Distress Indicators

Distress	Part of Structure
Anchorage movement	Concrete abutment structure
	Large piles
	Bridge piers
Elevation change	Spill
	Miter
Miter offset	Contract
	Angular
Bearing gaps	Spill
	Miter
Downstream movement	
Cracks	Girders
	Intercostals
	Skin plate
Leaks and boils	Skin leaks
	Spill and miter leaks
	Boils
Noise, jumping, vibration	Noise
	Jumping
	Vibration
Dents	Girders
	Intercostals
	Skin Plate
Corrosion	Girders
	Intercostals
	Skin Plate

1. *Chlorophyll a* (Chl *a*)

[illegible]

PART II: FIELD INSPECTION

Overview of the Inspection Form

Only minor updates have been made to the inspection form. The inspection form has been designed to provide flexibility in documenting a variety of field conditions on one standard form. Though there are nine pages in the inspection form, data for the last four are optional and need be entered only if structural analysis is required. Refer to the main report for more detail on the structural analysis portions of the inspection form (sheets 1 through 9 on pages 24 through 40 of the main report). The following section illustrates the updates of the condition index portions of the inspection form. Only sections where updates have occurred are listed. A complete, updated inspection form is in the Appendix to this supplement.

Update 1, Page 3

FACING DOWNSTREAM AT LIFTED GATE IDENTIFY GATE LEAF NUMBER _____

LEFT LEAF _____

RIGHT LEAF _____

Comments:

Record the orientation of the gate lock gates by drawing and identifying the left and right leaves as LEFT and RIGHT.

Update 2, Page 3

ELEVATIONS OF GATE LEAF

REFERENCE ELEVATION: LEFT LEAF _____ RIGHT LEAF _____

Comments:

ELEVATIONS OF GATE LEAVES: Record the elevation of a permanent benchmark on the concrete lockwall. In addition, the permanent benchmark should be identified on Page 3, OTHER COMMENTS.

Update 3, Page 3

ANCHORAGE SYSTEM MEASUREMENT (Fig. 1, 2, 3)

IS THE ANCHORAGE SYSTEM RIGID OR FLEXIBLE? R F _____

IF FLEXIBLE, LENGTH OF FLEXIBLE ANCHOR BAR: IN. _____

	CRACKED CONCRETE		EXHIBIT CORROSION Level 3 or greater	
	LEFT LEAF	RIGHT LEAF	LEFT LEAF	RIGHT LEAF
PARALLEL ARM:	(Y/N) _____	(Y/N) _____	(Y/N) _____	(Y/N) _____
PERP. ARM:	(Y/N) _____	(Y/N) _____	(Y/N) _____	(Y/N) _____

Comments:

ANCHORAGE SYSTEM MEASUREMENT: The parallel and perpendicular anchorage arms are parallel and perpendicular, respectively, to the lock chamber. Refer to the structural drawings of the anchorage system to determine if the anchorage system is rigid or flexible. Flexible anchorages are intended to move during gate operation and are often long embedded bars which are coated by an asphalt impregnated cork lining. Rigid anchorages are usually an embedded steel frame with little flexibility. The length of the embedded anchorage is measured from the face of the concrete to the end of the concrete embedment. Indicate the presence of excessive concrete cracking at location 1 (Figure 10, Greimann et al 1990) where the anchorage enters the concrete. Also, record the existence of Level 3 or greater corrosion on the anchorage system configuration. Excessive concrete spalling may indicate that a displacement occurred at this location at some point in time and may or may not show up at a current measurement. Small hairline cracks, probably caused by thermal expansion or contraction of the concrete, should be ignored in this analysis.

MITER AND QUOIN BEARING MEASUREMENTS

OFFSET OF MITER BLOCKS WITH GATE AT MITER (1' HEAD), (DIM. 4, 5)

		DISTANCE BELOW	
LOCATION	MEASUREMENT (in.)	TOP GIRDER (ft)	GATE DOWNSTREAM
TOP:	_____	_____	(L/R/NA)
DSWL:	_____	_____	(L/R/NA)

(DSWL = DOWNSTREAM WATER LEVEL WITH 1' HEAD ON GATE)

Bearing block width : (in.) _____

Comments:

MITER BLOCK OFFSET: The offset of miter blocks at the top of the gate, Dimension 4, and at the downstream water level (DSWL), Dimension 5, along with the vertical distance from the walkway to each measurement can be made with a ruler and tape. Record also the width of the bearing blocks. See Figure 11 in (Greimann et al 1990) for illustration of miter offsets. The gate leaves should be in the mitered position with 1 ft of head in the chamber to stabilize the gates. In addition, record the relative position of the leaves by indicating which leaf is further downstream, left (L) or right (R), at each measurement.

Sequence of Field Inspection

The following is a suggested sequence of data collection for pages 3 through 5 of the inspection form for two sets of miter gate leaves. If only one set of gates is to be inspected, start at Step 1 for the upper gate or Step 9 for the lower gate.

A three-person team is required; two on top of the lockwalls and one in the boat starting above the upper gate. The two people on top should independently read and record measurements and elevation readings. Verify data before proceeding to the next step. This may eliminate serious data errors. Begin inspection of the upper gate:

1. Set up
 - anchor measurement devices on both gate leaves of upper gate.
 - set level and transit on land side of chamber. The transit and level should be set in a location, on either lock wall, that provides the best field view for both gate leaves.
2. With gate in closed position (no head), one person rides near gate leaf to recessed position.
 - a. Take gate leaf elevations at recessed position.
 - b. Record anchor measurement at recessed position.
 - c. Observe and record noise, vibrations, and jumping of gate leaf as it is swung open and closed.
3. Repeat Step 2 on the other gate leaf.
4. During Steps 2 and 3, the boat person inspects upstream side of gate leaves for corrosion, dents, and cracks, and records the findings, then enters chamber when finished. The inspection personnel and lock operator should have good radio communications at all times when operating the lock.
5. Close gate leaves to near miter position (4 ft opening).
 - a. Take gate leaf elevations at this position.
 - b. Record anchor measurements at this position.
6. Close gate leaves to miter and drop water level in chamber 1 ft to stabilize gate and then hold level.
 - a. Take gate leaf elevations at this position.
 - b. Record anchor measurements at this position.
 - c. Record offset of miter blocks at top and DSL and which gate leaf is downstream.
 - d. Record gaps between bearing blocks at miter and both quins.
 - e. Inspect downstream side of gate for corrosion, dents, and cracks and record findings.

7. Place rulers near miter point on near gate leaf close to walkway and at DSWL. The rulers must be placed with the lowest number near the gate attachment.
 - a. Record longitudinal position reading of miter point from top rule and DSWL rule.
8. Lower water level in chamber so upper gate is under full head condition.
 - a. During emptying of chamber,
 - 1) top person observe miter block and record movement.
 - 2) top person observe both gate leaves and record any vibrations or noise.
 - 3) top person and boat person observe for leaks at changing water levels during emptying.
 - 4) boat person inspect and record corrosion, dents, and cracks on downstream side of gate.
 - b. At low water level, gate under full head pressure,
 - 1) top person get longitudinal position reading of miter point from top rule and DSWR rule.
 - 2) record anchor measurements with gate under full head pressure.

Begin inspection of the lower gate.

9. Lower water level in chamber.
 - a. Boat person inspect and record corrosion, dents, and cracks on upstream side.
 - b. Top people set up instruments and anchorage measurement devices.
10. With gate in closed position (no head), one person rides near gate leaf to recessed position.
 - a. Take gate leaf elevations at recessed position.
 - b. Record anchor measurement at recessed position.
 - c. Observe and record noise, vibrations, and jumping of gate leaf as gate leaf is swung open and closed.
11. Repeat Step 10 on the other gate leaf.
12. During Steps 10 and 11, the boat person inspects both quoin areas and the downstream side of the lower gate.
13. Open gate to near miter position (4 ft opening).
 - a. Take gate leaf elevations at this position.
 - b. Record anchor measurements at this position.

14. Close gate leaves to miter and fill water level in chamber 1 ft to stabilize gate and then hold level.
 - a. Take gate leaf elevations at this position.
 - b. Record anchor measurements at this position.
 - c. Record offset of miter blocks at top and DSWL and which gate leaf is downstream.
 - d. Record gaps between bearing blocks at miter and both quoins.
 - e. Inspect downstream side of gates for corrosion, dents and cracks and record findings.
15. Place rulers near miter point on near gate leaf close to walkway and at DSWL. The rulers must be placed with the lowest number near the gate attachment.
 - a. Record longitudinal position reading of miter point from top rule and DSWL rule.
16. Raise water level in chamber so lower gate is under full head condition.
 - a. During filling of chamber,
 - 1) top person observe miter block and record movement.
 - 2) top person observe both gate leaves and record any vibrations or noise.
 - 3) top person and boat person observe for leaks at changing water levels during filling.
 - 4) boat person inspect and record corrosion, dents, and cracks on downstream side of gate.
 - b. At full water level, gate under full head pressure,
 - 1) top person get longitudinal position reading of miter point from top rule and DSWL rule.
 - 2) record anchor measurements with gate under full head pressure.

An abbreviated form of the above detailed steps is presented graphically in Figure S1.




Figure S1. Graphical sequence of locking procedure.

PART III: CONDITION INDEX

The condition index involves "engineering judgment" and depends on the experience of the person making the evaluation. As such, condition index rules can be updated continually as judgements improve, more information is obtained, and more experience is gained. The experts took many factors into account as they evaluated the condition index. These factors include serviceability or performance and safety. It is the purpose of this chapter to show each of the distresses and the current updated rules and measurements. Equation numbers and section headings correspond to those in Part IV of the main report. (Note again, that the structural analysis is no longer a part of the condition index.)

A series of critical measurements, X , are made on each leaf to quantify the condition index. Experts were asked to interpret these measurements in light of the serviceability and safety of the gate and to assign limiting values, X_{max} , to the measurements. The individual distress condition index is quantified by

$$CI = 100(0.4) \times X_{max} \quad [4.1]$$

Updated values of X_{max} are included below for each distress as well as any errata that may have occurred in the original report (Greimann, Stecker, and Rens 1990).

Distress Code (1): Top Anchorage Movement

Update

Some embedded anchorage systems are designed to permit movement. These types of anchorage configurations are called flexible anchorage systems. In addition, the presence of significant anchorage corrosion should be considered as an influence to gate leaf condition. These concepts have been incorporated into current rules. The following paragraph should replace paragraph 93 of the main report:

93. For rigid and frame type anchorage systems, a displacement of 0.03 in. has been selected as the limiting motion at Location 1 for all gate sizes.

$$X_{max1} = 0.03 \text{ in.} \quad [4.2a]$$

The experts judged that motion greater than this could indicate a significant structural problem. For flexible anchorage systems, a stress change of 18,000 psi was selected as a reasonable working value. The corresponding maximum elastic motion has been selected conservatively, as

$$X_{max1} = 0.0006 (L) \text{ in.} \quad [4.2b]$$

where L is the length of embedded anchorage in inches. Any spalling or cracking of the concrete in this area will reduce the condition index in this area by a factor of 0.85. Additionally, a corroded anchorage configuration (level 3 or greater) will reduce the condition index by a factor of 0.85.

Errata

(none)

Distress Code (2): Elevation Change

Update

(none)

Errata

The following duplicate lines in paragraph 99 should be deleted:

The limiting X_{max} value for the change in quoin elevation has been judged to be

$$X_{max} = 0.05 \text{ ft} \quad [4.7]$$

Distress Code (3): Miter offset

Update

In earlier work, a maximum value of 2 in. of contact offset was permitted. Consideration was not made for the actual amount of bearing area. It was judged that 2 in. of contact offset would be excessive for a 5 or 6 in. set of bearing blocks. To account for variable width blocks, a 25 percent offset and 50 percent offset rule were incorporated as the limiting values of contact offset for horizontal and vertical gates, respectively. This gives 2 in. and 4 in. of contact offset for a 8 in. bearing block on a horizontal and vertical framed gate, respectively. The following paragraphs should replace paragraphs 105 and 108 in the main report.

105. Two types of miter offsets will be defined for horizontally framed leaves. The two types usually have different causes. The first type, contact offset, occurs when the miter bearing blocks are nominally parallel and plumb, but do not meet properly. Contact offset is measured by the maximum offset

$$X_c = \text{Maximum of absolute values } (O_1, O_2) \quad [4.12]$$

If X_c is too large, poor bearing conditions exist and eccentricity is introduced into the leaf girders. The experts judged the limiting case to be

$$X_{max} = 0.25 \text{ (BW)} \quad [4.13]$$

where BW is the bearing block width.

108. For a vertically framed gate, only the offset at the top of the miter block, O_1 , is measured.

$$X = O_1 \quad [4.17]$$

If X is too large, a poor bearing condition exists and eccentricity is introduced in the top girder as in the horizontally framed case. The limiting value for the vertically framed offset, which is not as critical as for horizontally framed, is

$$X_{\text{max}} = 0.5 \text{ (BW)} \quad [4.18]$$

The miter offset condition index applies to both leaves.

Errata

Equations 4.11 and 4.14 contained typographical errors. Replace these equations with the following:

$$O = [O_1(Y_1 - H) + O_2(H - Y_1)](Y_1 - Y_2) \quad [4.11]$$

$$X_1 = \text{Absolute value of } (O_1 - O_2) \quad [4.14]$$

Distress Code (4): Bearing Gaps

Update

Several distresses in the miter lock gate inspection program involve measurements at the top of the gate and at the down stream water level (DSWL). These measurements are then extrapolated to the sill by assuming a straight line equation. In the previous work, these assumptions were applied to quoin and miter gaps. After several inspections and meetings with Corps personnel, the extrapolation assumption did not seem reasonable for quoin gaps with either floating or fixed pintles. A better assumption would be to simply take the maximum of the top and DSWL measurements. Also, it was determined that the limiting value for quoin gaps should be a function of gate height. A limiting value of 0.25 in. was chosen for low gate leaves ($W/H = 2$), 0.125 in for high gate leaves ($W/H = 0.5$), and linear between for other gate heights. Rule and limiting value updates are listed below. **Omit Equations 4.23 and 4.24 of the main report.** The following paragraph should replace paragraph 112.

112. For a horizontally framed gate, measurements of the quoin block gap will also be made at the top of the gate, QG_1 , and at the water level, QG_2 , under a 1-ft head situation. The X_1 value for quoin block gaps is the maximum of the top and water level gap.

$$X_1 = \text{Maximum } (QG_1, QG_2) \quad [4.25]$$

A limiting value of 0.25 in. was chosen for low gate leaves ($W/H = 2$) and 0.125 in for high gate leaves ($W/H = 0.5$). For other heights, a linear equation that fits these two cases is used:

$$X_{\text{max}} = (W/H + 1)/12 \quad [4.26]$$

Any leaks at the quoin that follow the rising (emptying) water level will reduce the condition index of the quoin by the leak factor (Equation 4.22).

Errata

(none)

Distress Code (5): Downstream Movement

(no changes)

Distress Code (6): Cracks

(no changes)

Distress Code (7): Leaks and Boils

(no changes)

Distress Code (8): Dents

(no changes)

Distress Code (9): Noise, Jump and Vibration

(no changes)

Distress Code (10): Corrosion

(no changes)

PART IV: STRUCTURAL CONSIDERATIONS

Structural safety traditionally has been measured by a factor of safety. Hence, uncertainties in material properties and loading conditions are accounted for by selecting an appropriately high factor of safety to ensure a sufficient margin between the applied loads and the structural resistance. For example, the design criteria for miter lock gates typically require a factor of safety of two.

In this project, the structural adequacy of the gate can be evaluated in two ways: 1) structural analysis with a factor of safety calculation (optional), and 2) structural notes output for the subset of structural distresses (Table 2). As discussed in Part I, the structural analysis has limitations for condition rating because it does not reflect the current condition of the structure. For information on the structural analysis theory, refer to the original project report (Greimann, Stecker, and Rens 1990).

The purpose of the structural notes is to alert the engineer that a potential structural problem may be forming. The individual distresses are flagged, based on the experts judgement, as the condition index becomes low for any of the structural distresses (Table 3). For each of the structural distresses, a note will be generated for the summary report when the structural distress condition index falls into one of three different levels:

Level 1 Note:	$55 < CI < 70$
Level 2 Note:	$40 < CI < 55$
Level 3 Note:	$0 < CI < 40$

Values of the measurement X are also included in the notes. For example, for anchorage movement Location 1, the three levels of notes are

Level 1 Note: The perpendicular anchor bar was measured to move X inches and should be monitored.

Level 2 Note: The perpendicular anchor bar was measured to move X inches and could be a problem. Further investigation may be needed.

Level 3 Note: The perpendicular anchor bar was measured to move X inches. This is potentially a structural hazard. Further investigation is needed.

The importance of the notes must be emphasized. The condition index must be a trigger mechanism for structural concerns since the structural condition index is no longer an integral part of the condition assessment.

Summary Report

Two example summary reports that detail the individual distress condition indexes and structural notes are included on the following pages. In Example 1, the optional structural analysis has been performed.

SUMMARY REPORT

PROJECT NAME:

Test1 project

LOCATION:

gate1

Town, USA

INSPECTION DATE: 10 25 92

INSPECTED BY: G, S, R

The overall condition has been analysed and compiled in the following indices:

CONDITION INDEX:

Right Leaf: 41

Left Leaf: 37

CONDITION INDEX

Distress	Left Leaf	Right Leaf
** ANCHOR SYSTEM	: 29	51
DOWNSTREAM MOVEMENT	: 63	63
** NOISE JUMP VIBRATION	: 70	70
** MITER OFFSET	: 7	7
GAP	: 93	82
** CORROSION	: 40	29
** DENTS	: 40	40
** CRACKS	: 40	40
LEAKS & BOILS	: 54	73
ELEVATION CHANGE	: 69	83
CI	: 37	41

Structural Notes

** ANCHOR SYSTEM

At location 1 on the left leaf, the PARALLEL anchor bar was measured to move 0.030 inches.

This is potentially a structural hazard. Further investigation is needed.

Anchor corrosion has occurred.

Cracked concrete has occurred.

** ANCHOR SYSTEM

At location 1 on the left leaf, the PERPENDICULAR anchor bar was measured to move 0.015 inches and could be a problem. Further investigation may be needed.

Cracked concrete has occurred.

** ANCHOR SYSTEM

At location 1 on the right leaf, the PARALLEL anchor bar was measured to move 0.008 inches and should be monitored.

Anchor corrosion has occurred.

** ANCHOR SYSTEM

At location 1 on the right leaf, the PERPENDICULAR anchor bar was measured to move 0.007 inches and should be monitored.

Cracked concrete has occurred.

** NOISE JUMP VIBRATION

Jumping has occurred on the right leaf. This could be a structural hazard.

** NOISE JUMP VIBRATION

Jumping has occurred on the left leaf. This could be a structural hazard.

** MITER OFFSET

The contact offset was measured to be 72 percent of the bearing block width. This is potentially a structural hazard. Further investigation is needed.

** CORROSION

Level 3 girder corrosion was recorded on the left leaf. Further investigation may be needed.

**CORROSION

Level 4 girder corrosion was recorded on the right leaf. This is potentially a structural hazard. Further investigation is needed.

** DENTS

1 girder dent(s) were recorded on the left leaf. Further investigation is necessary.

** DENTS

1 girder dent(s) were recorded on the right leaf. Further investigation may be necessary.

** CRACKS

1 girder crack(s) were recorded on left leaf. Further investigation may be needed.

** CRACKS

1 girder crack(s) were recorded on the right leaf. Further investigation may be needed.

STRUCTURAL FACTOR OF SAFETY

LC	INTERCCSTAL	PNL #	SKIN	PNL #	GIRDER	GRDR #
1	2.7	10	2.7	6	1.7	7
2	2.7	10	2.7	6	1.9	7
3	144.0	2	108.0	2	100.0	2
4	55.4	2	41.5	1	37.5	2
6	2.6	10	2.5	6	1.8	7

Miter Gate Structure:

TEST 2 - GATE2

Mon Jan 25 1993

SUMMARY REPORT

PROJECT NAME:

Test2 project

LOCATION:

Gate2

Town, USA

INSPECTION DATE: 06/21/91

INSPECTED BY: Team

The overall condition has been analyzed and compiled in the following indices:

CONDITION INDEX:

Right leaf: 51

Left Gate: 55

CONDITION INDEX

Distress	Left leaf	Right leaf
** ANCHOR SYSTEM :	71	32
DOWNSTREAM MOVEMENT :	63	63
NOISE JUMP VIBRATION :	100	100
MITER OFFSET :	85	85
GAP :	93	82
** CORROSION :	40	74
** DENTS :	91	40
** CRACKS :	40	91
LEAKS & BOILS :	73	87
ELEVATION CHANGE :	69	83
CI :	55	51

Structural Notes

** ANCHOR SYSTEM

At location 1 on the right leaf, the PERPENDICULAR anchor nut was measured to move 0.032 inches.

This may be a structural hazard. Further investigation is needed.
Anchor corrosion has occurred.

** CORROSION

Level 3 girder corrosion was recorded on the left leaf.
Further investigation may be needed.

** DENTS

1 girder dent(s) were recorded on the right leaf.
Further investigation may be necessary.

** CRACKS

1 girder crack(s) were recorded on the left leaf.
Further investigation may be needed.

REFERENCES

Greimann, L., and J. Stecker. 1990. Maintenance and Repair of Steel Sheet Pile Structures, Technical Report REMR-OM-9, US Army Corps of Engineers, Washington, DC.

Greimann, L., J. Stecker, and K. Rens. 1990. Management System for Miter Lock Gates, Technical Report REMR-OM-08, US Army Corps of Engineers, Washington, DC.

US Army Corps of Engineers. 1987. Microsoft Version, CMINV- Miter Gate Investigation.

US Army Corps of Engineers. 1992. Reliability Assessment of Navigation Structures, Engineer Technical Letter No. 1110-2-532.

APPENDIX A: SAMPLE INSPECTION FORM

U.S. ARMY CORPS OF ENGINEERS
MITER LOCK GATE STRUCTURE INSPECTION

PAGE 1

NAME OF CIVIL WORKS PROJECT:

LOCATION OF CIVIL WORKS PROJECT:

(1. Body of water, 2. Nearest town)

1. _____
2. _____

INSPECTION DATE: _____ INSPECTED BY: _____

GATE IDENTIFICATION:

1. Upper gate
2. Lower gate GATE ID (no.) _____

TYPE OF STRUCTURAL FRAMING PRESENT:

1. Horizontal
2. Vertical STRUCTURE TYPE (no.) _____

TYPE OF PINTLE:

1. Fixed
2. Floating PINTLE SYSTEM (no.) _____

TYPE OF SKIN PLATE:

1. Single
2. Double SKIN TYPE (no.) _____

LENGTH OF LOCK CHAMBER: (ft) _____

WIDTH OF LOCK CHAMBER: (ft) _____

HEIGHT OF GATE LEAF: (ft) _____

WIDTH OF GATE LEAF: (ft) _____

PRESENT POOL WATER LEVELS: (ft) UPPER _____ LOWER _____

RECORD LOW WATER LEVEL: (ft) UPPER _____ LOWER _____

RECORD HIGH WATER LEVEL: (ft) UPPER _____ LOWER _____

DO YOU ROUTINELY DEWATER LOCK CHAMBER? (Y/N) _____ IF YES, WHAT

YEAR WAS THE LOCK LAST DEWATERED? _____ INTERVAL PERIOD: _____

CONSTRUCTION DATE: _____ OTHER COMMENTS: _____

U.S. ARMY CORPS OF ENGINEERS
MITER LOCK GATE STRUCTURE INSPECTION

PAGE 2

ARE ORIGINAL GATE LEAVES CURRENTLY IN PLACE? (Y/N) _____

IF NOT, IDENTIFY CURRENT GATE LEAF HISTORY: _____

ARE DRAWINGS AVAILABLE FOR GATE LEAVES IN PLACE? (Y/N) _____

ARE THE DRAWINGS INCLUDED WITH THIS FILE? (Y/N) _____

PAST 10 YEAR HISTORY

MAJOR MAINTENANCE, REPAIRS, OR OTHER MODIFICATIONS

	<u>DATE</u>	<u>DESCRIPTION</u>
(1):	_____	_____
(2):	_____	_____
(3):	_____	_____
(4):	_____	_____

PREVIOUS INSPECTIONS OR STRUCTURAL REVIEW (attach if available)

	<u>DATE</u>	<u>DESCRIPTION</u>
(1):	_____	_____
(2):	_____	_____
(3):	_____	_____
(4):	_____	_____

TYPE OF FENDER PROTECTION AND CONDITION OF FENDERS:

TYPE OF WALKWAY ON GATE LEAF AND CONDITION OF WALKWAY:

OTHER COMMENTS:

U.S. ARMY CORPS OF ENGINEERS
MITER LOCK GATE STRUCTURE INSPECTION

PAGE 3

FACING DOWNSTREAM AT UPPER GATE, IDENTIFY GATE LEAVES AS N,S,E, or W

LEFT LEAF = _____
 RIGHT LEAF = _____

OPENING AND CLOSING OF GATE LEAVES

	LEFT LEAF	% CLOSED	RIGHT LEAF	% CLOSED
DO THE DIAGONALS FLAP?	(Y/N) _____	_____	(Y/N) _____	_____
DOES THE GATE JUMP?	(Y/N) _____	_____	(Y/N) _____	_____
IS THERE GATE NOISE?	(Y/N) _____	_____	(Y/N) _____	_____
DOES THE GATE VIBRATE?	(Y/N) _____	_____	(Y/N) _____	_____

ELEVATIONS OF GATE LEAF

REFERENCE ELEVATION:	LEFT LEAF	RIGHT LEAF
	NEAR MITER	MITER FULL HEAD
LEFT LEAF QUOIN METER	RECESSED _____ _____	MITER 1 ft HEAD _____ _____
RIGHT LEAF QUOIN MITER	_____ _____ _____	_____ _____ _____

ANCHORAGE SYTEM MEASUREMENT (Dim. 1, 2, 3)

IS THE ANCHORAGE SYSTEM RIGID OR FLEXIBLE? (R/F) _____
 IF FLEXIBLE, LENGTH OF FLEXIBLE ANCHOR BAR: (in./NA) _____

	CRACKED CONCRETE		ANCHOR CORROSION (Level 3 or greater)	
	LEFT LEAF	RIGHT LEAF	LEFT LEAF	RIGHT LEAF
PARALLEL ARM:	(Y/N) _____	(Y/N) _____	(Y/N) _____	(Y/N) _____
PREP. ARM:	(Y/N) _____	(Y/N) _____	(Y/N) _____	(Y/N) _____
LEFT LEAF		NEAR	MITER	MITER
ARM DIM. (in.)	RECESSED	MITER	1 ft HEAD	FULL HEAD
PARALLEL 1:	_____	_____	_____	_____
PARALLEL 2:	_____	_____	_____	_____
PARALLEL 3:	_____	_____	_____	_____
PERP. 1:	_____	_____	_____	_____
PERP. 2:	_____	_____	_____	_____
PERP. 3:	_____	_____	_____	_____
RIGHT LEAF		NEAR	MITER	MITER
ARM DIM. (in.)	RECESSED	MITER	1 ft HEAD	FULL HEAD
PARALLEL 1:	_____	_____	_____	_____
PARALLEL 2:	_____	_____	_____	_____
PARALLEL 3:	_____	_____	_____	_____
PERP. 1:	_____	_____	_____	_____
PERP. 2:	_____	_____	_____	_____
PERP. 3:	_____	_____	_____	_____

MITER AND QUOIN BEARING MEASUREMENTS

OFFSSET OF MITER BLOCKS WITH GATE AT MITER (1 ft HEAD), (DIM. 4, 5)

LOCATION	MEASUREMENT (in.)	DISTANCE BELOW TOP GIRDER (ft)	GATE DOWNSTREAM (L/R/NA)
TOP:	_____	_____	_____
DSWL:	_____	_____	_____

(DSWL = DOWNSTREAM WATER LEVEL WITH 1 ft HEAD ON GATES)

Bearing block width: (in.) _____

GAP BETWEEN BEARING BLOCKS WITH GATES AT MITER (1 ft HEAD), (DIM. 6, 7)

LOCATION	MEASUREMENT (in.)	DISTANCE BELOW TOP GIRDER (ft)
LEFT QUOIN @ TOP:	_____	_____
LEFT QUOIN @ DSWL:	_____	_____
RIGHT QUOIN @ TOP:	_____	_____
RIGHT QUOIN @ DSWL:	_____	_____
MITER @ TOP:	_____	_____
MITER @ DSWL:	_____	_____

LONGITUDINAL POSITION OF MITER POINT (DIM. 8)

LOCATION	MEASUREMENT (in.) 1 ft HEAD FULL HEAD	DISTANCE BELOW TOP GIRDER (ft)
TOP:	_____	_____
DSWL:	_____	_____

LOCK CHAMBER FILLING (OR EMPTYING)

DOES THE GATE VIBRATE? LEFT LEAF: (Y/N) _____
RIGHT LEAF: (Y/N) _____

DOES A LEAK FOLLOW THE RISING (OR EMPTYING) LEFT QUOIN: (Y/N) _____
WATER LEVEL AND THEN CLOSE AGAIN AS THE MITER: (Y/N) _____
WATER CONTINUES TO RISE (EMPTY)? RIGHT QUOIN: (Y/N) _____

DOES THE GAP BETWEEN MITER BLOCKS CHANGE? (Y/N) _____

IF YES, SELECT FROM THE FOLLOWING CHOICES THE MOST ACCURATE DESCRIPTION
OF THE CHANGE. (No.) _____

1. TOP GAP INITIALLY OPEN BUT CLOSES UNDER FULL HEAD.
2. TOP GAP OPENS WIDER BUT CLOSES UNDER FULL HEAD.
3. TOP GAP OPENS AND REMAINS OPEN.
4. TOP OF MITER IS CLOSED BUT GAP OPENS BETWEEN WATER LINE AND TOP.
5. TOP OF MITER IS CLOSED AND GAP BETWEEN WATER LINE AND TOP CLOSES.

ESTIMATE THE MAXIMUM WIDTH OF GAP (in.) _____

ESTIMATE THE LOCATION OF THE MAXIMUM GAP FROM TOP GIRDER (ft) _____

U.S. ARMY CORPS OF ENGINEERS
MITER LOCK GATE STRUCTURE INSPECTION

PAGE 5

OBSERVATIONS FROM BOAT

CORROSION AT SPLASH ZONE (LEVEL 0,1,2,3,4, or 5)

	LEFT LEAF		RIGHT LEAF	
	UPSTREAM	DOWNSTREAM	UPSTREAM	DOWNSTREAM
SKIN:	_____	_____	_____	_____
GIRDER:	_____	_____	_____	_____
INTERCOSTAL:	_____	_____	_____	_____

DENTS -- SKIN PLATE (S), GIRDERS (G), OR INTERCOSTALS (I)

	LEAF L or R	COMPONENT S, G, OR I	LOCATION, DIST. FROM: (ft)		SIZE (ft)	
			TOP GIRDER	QUOIN	HEIGHT	LENGTH
(1):	_____	_____	_____	_____	_____	_____
(2):	_____	_____	_____	_____	_____	_____
(3):	_____	_____	_____	_____	_____	_____
(4):	_____	_____	_____	_____	_____	_____
(5):	_____	_____	_____	_____	_____	_____

CRACKS -- SKIN PLATE (S), GIRDERS (G), OR INTERCOSTALS (I)

	LEAF L or R	COMPONENT S, G, OR I	LOCATION, DIST. FROM: (ft)		SIZE (ft)	
			TOP GIRDER	QUOIN	HEIGHT	LENGTH
(1):	_____	_____	_____	_____	_____	_____
(2):	_____	_____	_____	_____	_____	_____
(3):	_____	_____	_____	_____	_____	_____
(4):	_____	_____	_____	_____	_____	_____
(5):	_____	_____	_____	_____	_____	_____

BEARING BLOCK LEAKS @ LEFT LEAF (L), MITER (M), RIGHT LEAF (R)
TYPE -- L,M,R DISTANCE FROM TOP GIRDER (ft) LENGTH (ft)

(1):	_____	_____	_____
(2):	_____	_____	_____
(3):	_____	_____	_____
(4):	_____	_____	_____
(5):	_____	_____	_____

SKIN LEAKS @ LEFT LEAF (L), RIGHT LEAF (R)

	GATE L or R	TYPE (H)ORIZ. OR (V)ERT	SHORTEST DISTANCE FROM: (ft)		
			TOP GIRDER	QUOIN	LENGTH
(1):	_____	_____	_____	_____	_____
(2):	_____	_____	_____	_____	_____
(3):	_____	_____	_____	_____	_____
(4):	_____	_____	_____	_____	_____
(5):	_____	_____	_____	_____	_____

BOILS @ LEFT LEAF (L), RIGHT LEAF (R), MITER (M)

	TYPE (L,R, or M)	DISTANCE FROM QUOIN (ft)
(1):	_____	_____
(2):	_____	_____
(3):	_____	_____
(4):	_____	_____
(5):	_____	_____

U.S. ARMY CORPS OF ENGINEERS
MITER LOCK GATE STRUCTURE SAFETY INSPECTION

PAGE 6

Calculation date: _____ Calculated by: _____

REQUIRED OVERALL VERTICAL GEOMETRY

Positive elevation of sill above any datum, ELSILL (ft): _____
Sill to bottom of skin plate, GBOT (ft): _____
Sill to overflow elevation at top of gate, GTOP (ft): _____

REQUIRED OVERALL LEAF GEOMETRY

Leaf between contact points, GLEMG (ft): _____
Gate leaf slope, GSLOPE (ft): _____
Working line to downstream edge of girder webs, GWORKL (ft): _____
Quoin contact point to gudgeon pin, GQUOIN (ft): _____
Working line to gudgeon pin (positive when contact point is downstream from
gudgeon pin), GPIN1 (ft): _____

COMMON GIRDER GEOMETRY DIMENSIONS

Girder contact point to center of nearest end diaphragm along working line,
DQPED (in): _____
Center of end diaphragm at miter end of gate to miter contact point along
working line, DEDMP (in): _____
Bottom girder downstream flange extension below web centerline,
BGDFD (in): _____

GIRD3ER ELEVATIONS

Number of girders in the gate leaf, NGIRDS: _____
Girder Number, NGIRD Vertical distance above sill, VD (ft)

_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

GIRDER DIAPHRAGM SPACING

Top girder of similar pnl NPANLI	Bottom girder of similar pnl NPANLN	Spaces between end diaphragms NDS	Intcostl spaces btwn adj dphms NIS
_____	_____	_____	_____

DEAD AND LIVE LOADS:

Additional dead load, including ice, mud walkway, gusset plates, etc,

ADEAD (lb): _____

Quoin contact point to centroid of ADEAD along working line,

XDEAD (ft): _____

Downstream edge of girder web to centroid of ADEAD,

ZDEAD (in.): _____

Bouyancy force acting on dry weight of gate,

ABUOY (lb): _____

Quoin contact point to centroid fo ABUOY along working line,

XBOUY (ft): _____

Downstream edge of girder web to centroid of ABUOY,

ZBOUY (in.): _____

Concentrated live load, including walkway and bridgeway,

ALIVE (lb): _____

REQUIRED WATER ELEVATIONS -- (FEET ABOVE ELSILL)

Elevation of upper pool, ELUP (ft): _____

Elevation of lower pool, ELLP (ft): _____

Full submerge elevation, ELFS (ft): _____

Operating water elevations, ELCW (ft): _____

STEEL YIELD STRENGTH (KSI):

Miscellaneous steel yield strength _____

Webs	Flanges	Skin	Stiffeners	Intercostals	Quoin	Diaphragms
_____	_____	_____	_____	_____	_____	_____

U.S. ARMY CORPS OF ENGINEERS
MITER LOCK GATE STRUCTURE SAFETY INSPECTION

PAGE 8

GIRDER WEB THICKNESS (in.)

Groups of similar girders		Web end zone	Web center zone
Top girder	Bottom girder	thickness	thickness
NGIRDI	NGIRDN	GWET	GWCT
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

GIRDER FLANGES, UPSTREAM (in.)

Groups of similar girders		Upstream flange widths		
Top Number	Bottom Number			
NGIRDI	NGIRDN	GUFEW	GUF34W	GUF4CW
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Upstream flange thickness

		Upstream flange cover plate		
		Distance from Quoin	Width	Thickness
GUFFET	GUFCT	GUCPX	GUCPW	GUCPT
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

GIRDER FLANGES, DOWNSTREAM (in.)

Groups of similar girders		Downstream flange widths	
Top Number	Bottom Number		
NGIRDI	NGIRDN	GDFEW	GDPCW
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Downstream flange thickness

		Downstream flange cover plate		
		Distance from Quoin	Width	Thickness
GDFET	GDFCT	GDCPX	GDCPW	GDCPT
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

GIRDER FLANGE COORDINATES (in.)

Groups of similar girders		Flange splice distance from Quoin	
Top No.	Bottom No.	Upstream	Downstream
NGIRDI	NGIRDN	GUPX4	GDPX5
_____	_____	_____	_____
_____	_____	_____	_____

GIRDER WEB STIFFENERS (in.)

Groups of similar girders		No. trans. stiffnr	No. of long
Top No.	Bottom No.	spcs btwn intrmdt dphr	stiffnr pairs
NGIRDI	NGIRDN	NGWTS	NGLS
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Longitudinal stiffener geometry

Stiffener number 1			Stiffener number 2			Stiffener number 3		
Width Thickness			Width Thickness			Width Thickness		
GLS1D	GLS1W	GLS1T	GLS2D	GLS2W	GLS2T	GLS3D	GLS3W	GLS3T
_____	_____	_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____	_____	_____

INTERCOSTAL AND SKIN PLATE GEOMETRY (in.)

Groups of similar intercostals

Top girder no.	Bottom girder no.	Skin plate thickness
NPANLI	NPANLN	SPT
_____	_____	_____
_____	_____	_____
_____	_____	_____

Depth (perp to skin)	Stem thickness	Fling width	Fling thickness
ODI	STEMT	FWI	FTI
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

DISTRIBUTION

Chief of Engineers

ATTN: CECW-OM-O (13)

US Army Engineer Division

ATTN: CELMV-CO-O (2)

ATTN: CENPD-CO-O (2)

ATTN: CEMRD-MO-O (2)

ATTN: CEORD-CO-O (2)

ATTN: CENCD-CO-O (2)

ATTN: CESAD-CO-O (2)

ATTN: CESWD-CO-O (2)

US Army Engineer District

ATTN: CELMS-OD-R (3)

ATTN: CELMK-OD-M (5)

ATTN: CENNPP-Oi (14)

ATTN: CENPW-OP (8)

ATTN: CENPS-OP (5)

ATTN: CEMRO-GP (8)

ATTN: CEMRK-OD (4)

ATTN: CEORN-OR (10)

ATTN: CENCE-CO (3)

ATTN: CESAM-OP (10)

ATTN: CESAS-OP (5)

ATTN: CESAC-CO-M (4)

ATTN: CESAW-CO (3)

ATTN: CESWP-OD (5)

ATTN: CESWL-CO (9)

ATTN: CWSWT-OD (10)

US Army Engineer Division

ATTN: CENPD-PE-HD (59)

(Hydroelectric Design Center)

CEWES-SC-A (2)

CECER-IML (2)

CECER-FMM (2)

Defense Technical Info. Center 22304

ATTN: DTIC-FAB (2)

200

4/93